



NEWS RELEASE

FOR IMMEDIATE RELEASE

Contact: Anthony Toderian
 Senior Media Relations Officer
 CSA Group
 T: 416-747-2620
 E: anthony.toderian@csagroup.org

**CSA INTERNATIONAL AND FIESTA BARBEQUES ANNOUNCE
 A VOLUNTARY RECALL TO INSPECT AND REPAIR GAS GRILLS**

Toronto, ON – November 7, 2008 - In cooperation with CSA International, Fiesta Barbeques of Brampton, Ontario today announce that there may be an assembly problem with certain “Blue Ember Gas Grills”. This safety notice involves Blue Ember brand liquid propane (LP) or natural gas outdoor barbeques, Models FG50057 and FG50069. Approximately 34,000 units were distributed across Canada.

The barbeques may be assembled improperly exposing the burner hoses to excessive heat, and may pose a fire and burn hazard to users. Fiesta has received 16 reports of barbeque fires in Canada that may have been caused by the burner hose being placed behind the heat shield. No injuries have been reported.


The affected model and serial numbers are listed below. The model and serial numbers are printed on a rating plate label on the rear of the grill. The cabinet style grill has two doors and is silver-coloured and black or silver-coloured and gray. “Blue Ember” is printed on the grill’s hood.

Model Numbers	Serial Numbers	
FG50057 or FG50069	08K000769-08K002176	08K031493-08K032900
	08K002305-08K003072	08K038197-08K038964
	08K003075-08K006914	08K042640-08K042760
	08K007811-08K012034	08K042763-08K043658
	08K012163-08K016002	08K043914-08K044041
	08K014595-08K014722	08K047884-08K048267
	08K015363-08K015874	08K048662-08K048789
	08K016389-08K017796	08K051670-08K051925
	08K018053-08K018308	08K052054-08K052181
	08K019333-08K019844	08U033401-08U033528
	08K019973-08K024964	08U041309-08U041564
	08K024984-08K026485	08U042645-08U042772
	08K026486-08K026614	08U047525-08U048164
	08K028805-08K030340	08U048172-08U048792
	08K030348-08K031323	

The barbeques were sold nationwide at various home centres and retailers from November 2007 through June 2008.

Consumers should immediately stop using the barbeques, and inspect the burner hoses to make sure they have been properly assembled. If the hose is to the rear of the installed heat shield, the barbeque has been improperly assembled and consumers should contact Fiesta for replacement hoses, assembly instructions and, if necessary, for assistance in examining the grill.

For additional information, contact Fiesta toll free at (866) 956-0396 between 7 a.m. and 5 p.m. Eastern Time, Monday through Friday, visit Fiesta's website at www.blueembergrillsgrills.com , or email Fiesta at nguyen@fiestabbq.com.



About CSA International

CSA International is a provider of product testing and certification services for electrical, mechanical, plumbing, gas and a variety of other products. Recognized in the U.S., Canada and around the world, CSA International certification marks appear on billions of products worldwide. CSA International is a division of CSA Group, which also includes CSA, a leading solutions based standards organization, providing standards development, application products, training and advisory services; and OnSpeX, a provider of consumer product evaluation, inspection and advisory services for retailers and manufacturers. For more information, visit www.csa-international.org